DESCRIPTION

Grease -B- Gone is a extremely powerful & effective formulation that cuts through grease easily inside drain lines and grease traps. Controls odor by eliminating slime and scum deposits. Keeps lines



free-flowing and fresh-smelling. Use to clean walls, quarry tile, greasy kitchen floors and anywhere grease is a problem. Ideal for grease trap maintainers. Safe for all metal pipes.

CODE:ENV-1017



APPLICATIONS

USAGE

NOTE: Do not freeze the product. Some stains like rust or permanent ink stains may be impossible to remove.

- Apply a small amount of product to the required area to be cleaned.
- Slightly rub with a brush.
- Allow to stand for few minutes.
- Rinse or wipe clean.
- Repeat the process for extremely tough or old stain.



- Drains
- Grease Traps
- Kitchen grease
- Equipments
- Floors
- Walls
- Sewage & Industrial Plants



Grease B Gone is safe and non--corrosive on all metal pipes. None of our ingredients contains phosphates which makes them safe for aquatic enviornment.

BENEFITS

- Ideal for grease trap maintenance.
- Controls odor by eliminating slime and scum deposits
- · Safe and easy to use
- Alkaline pH enhances cleaning power.
- Non-flammable
- Pleasant Prairie Sage fragrance.
- Safe & non-corrosive on metals.









SPECIFICATIONS

Physical Form Liquid
Colour Green
Odour Prairie Sage
pH (1 g/L solution) 11-11.5
Flammability Non-Flammable

STORAGE







Store away from direct sunlight and heat



Store in original container with closed lid, away from incompatible materials such as strong acids.

SHELF LIFE: 1 year minimum after opening

PACKAGING



This packaging is made from high density polyethylene (HDPE) one of the most commonly and easily recycled plastics!

Concentrated products save on packaging, energy, and emissions associated with transport. Instead of shipping mostly water, we are sending you a super concentrated product that you simply dilute with tap water. This allows us to pass the savings on to you!

AVAILABLE IN: 4L, 20L, 205L

PRECAUTIONS

Wash hands thoroughly after handling. Do not breathe mists, vapours or spray. Wear eye and face protection. Wear protective gloves. Wear protective clothing. Contaminated work clothing should not be allowed out of the workplace.

Refer SDS for more information.



